

LTR 97 SERVICE BULLETIN INDEX

This Index is available on the Internet at: <http://nsd.es.northropgrumman.com/> (Click Support)

SB NUMBER/ FILE NUMBER	REV #.	REVISION DATE	ERA NO.	SUBJECT																					
SB97-34-04 SB1635R0 FOG VG/DG	Rev 0	Apr 4/01	ECO 061167	FOG VG/DG – MOD 4 Update hardware to minimize the potential for a system shutdown caused by interrupts to the 28 vdc backup voltage. (Level II): <table border="0"> <tr> <td><u>From</u></td> <td><u>To</u></td> <td></td> </tr> <tr> <td>142830-1000</td> <td>Mark MOD 4</td> <td>FOG VG/DG Unit</td> </tr> <tr> <td>142832-3001</td> <td>142832-3002</td> <td>FOG VG/DG Assy</td> </tr> <tr> <td>142832-3101</td> <td>142832-3102</td> <td>FOG VG/DG Assy</td> </tr> <tr> <td>142832-3200</td> <td>142832-3202</td> <td>FOG VG/DG Assy</td> </tr> <tr> <td>142832-3301</td> <td>142832-3302</td> <td>FOG VG/DG Assy</td> </tr> <tr> <td>142843-3000</td> <td>142843-3100</td> <td>Front Panel</td> </tr> </table>	<u>From</u>	<u>To</u>		142830-1000	Mark MOD 4	FOG VG/DG Unit	142832-3001	142832-3002	FOG VG/DG Assy	142832-3101	142832-3102	FOG VG/DG Assy	142832-3200	142832-3202	FOG VG/DG Assy	142832-3301	142832-3302	FOG VG/DG Assy	142843-3000	142843-3100	Front Panel
<u>From</u>	<u>To</u>																								
142830-1000	Mark MOD 4	FOG VG/DG Unit																							
142832-3001	142832-3002	FOG VG/DG Assy																							
142832-3101	142832-3102	FOG VG/DG Assy																							
142832-3200	142832-3202	FOG VG/DG Assy																							
142832-3301	142832-3302	FOG VG/DG Assy																							
142843-3000	142843-3100	Front Panel																							
SB97-34-05 SB1640R2 FOG VG/DG	Rev 2	Nov 29/01	None	FOG VG/DG – Software update to –1200 SW <table border="0"> <tr> <td><u>From</u></td> <td><u>To</u></td> <td></td> </tr> <tr> <td>142830-0000</td> <td>142830-0001</td> <td>FOG VG/DG Unit</td> </tr> <tr> <td>142830-2000</td> <td>142830-2001</td> <td>FOG VG/DG Unit</td> </tr> </table>	<u>From</u>	<u>To</u>		142830-0000	142830-0001	FOG VG/DG Unit	142830-2000	142830-2001	FOG VG/DG Unit												
<u>From</u>	<u>To</u>																								
142830-0000	142830-0001	FOG VG/DG Unit																							
142830-2000	142830-2001	FOG VG/DG Unit																							
SB97-34-06 SB1643R0 FOG VG/DG	Rev 0	Nov 7/01	ECO 061331	FOG VG/DG – Hardware and software update to –1200 software <table border="0"> <tr> <td><u>From</u></td> <td><u>To</u></td> <td></td> </tr> <tr> <td>142830-1000</td> <td>142830-1001</td> <td>FOG VG/DG Unit</td> </tr> <tr> <td>125456</td> <td>125456-1001</td> <td>Interface Module</td> </tr> <tr> <td>125456-2000</td> <td>125456-1001</td> <td>Interface Module</td> </tr> <tr> <td>142843-3000</td> <td>142843-3200</td> <td>Front Plate Assy.</td> </tr> <tr> <td>142843-3100</td> <td>142843-3200</td> <td>Front Plate Assy.</td> </tr> </table>	<u>From</u>	<u>To</u>		142830-1000	142830-1001	FOG VG/DG Unit	125456	125456-1001	Interface Module	125456-2000	125456-1001	Interface Module	142843-3000	142843-3200	Front Plate Assy.	142843-3100	142843-3200	Front Plate Assy.			
<u>From</u>	<u>To</u>																								
142830-1000	142830-1001	FOG VG/DG Unit																							
125456	125456-1001	Interface Module																							
125456-2000	125456-1001	Interface Module																							
142843-3000	142843-3200	Front Plate Assy.																							
142843-3100	142843-3200	Front Plate Assy.																							
SB97-34-07 SB1645R0 LHAS	Rev 0	Jan 18/02	None	LHAS – Software update to –1200 software <table border="0"> <tr> <td><u>From</u></td> <td><u>To</u></td> <td></td> </tr> <tr> <td>465821-01-01</td> <td>465821-03-01</td> <td>LHAS Unit</td> </tr> <tr> <td>465821-01-02</td> <td>465821-03-02</td> <td>LHAS Unit</td> </tr> <tr> <td>465821-02-01</td> <td>465821-03-01</td> <td>LHAS Unit</td> </tr> <tr> <td>465821-02-02</td> <td>465821-03-02</td> <td>LHAS Unit</td> </tr> <tr> <td>142830-1000</td> <td>142830-1001</td> <td>FOG VG/DG Unit</td> </tr> </table>	<u>From</u>	<u>To</u>		465821-01-01	465821-03-01	LHAS Unit	465821-01-02	465821-03-02	LHAS Unit	465821-02-01	465821-03-01	LHAS Unit	465821-02-02	465821-03-02	LHAS Unit	142830-1000	142830-1001	FOG VG/DG Unit			
<u>From</u>	<u>To</u>																								
465821-01-01	465821-03-01	LHAS Unit																							
465821-01-02	465821-03-02	LHAS Unit																							
465821-02-01	465821-03-01	LHAS Unit																							
465821-02-02	465821-03-02	LHAS Unit																							
142830-1000	142830-1001	FOG VG/DG Unit																							
SB97-34-08 SB1661R0 FOG VG/DG	Rev 0	Apr 17/03	None	FOG VG/DG Unit – Replace the Synchro Interface Module (SIM) to resolve Roll Jitter anomaly.(Level 2) <table border="0"> <tr> <td><u>From</u></td> <td><u>To</u></td> <td></td> </tr> <tr> <td>142830-0001</td> <td>142830-0001</td> <td>MOD 3</td> </tr> <tr> <td>142830-1001</td> <td>142830-1001</td> <td>MOD 1</td> </tr> <tr> <td>142830-200X</td> <td>142830-200X</td> <td>MOD 3</td> </tr> <tr> <td>125453-1000</td> <td>125453-1002</td> <td>SIM</td> </tr> <tr> <td>125453-1001</td> <td>125453-1002</td> <td>SIM</td> </tr> </table>	<u>From</u>	<u>To</u>		142830-0001	142830-0001	MOD 3	142830-1001	142830-1001	MOD 1	142830-200X	142830-200X	MOD 3	125453-1000	125453-1002	SIM	125453-1001	125453-1002	SIM			
<u>From</u>	<u>To</u>																								
142830-0001	142830-0001	MOD 3																							
142830-1001	142830-1001	MOD 1																							
142830-200X	142830-200X	MOD 3																							
125453-1000	125453-1002	SIM																							
125453-1001	125453-1002	SIM																							
SB97-34-09 SB1684R0 LHAS	Rev 0	Feb 13/07	28990	LHAS – Wiring change - Amendment C <table border="0"> <tr> <td><u>From</u></td> <td><u>To</u></td> <td></td> </tr> <tr> <td>456821-03-01</td> <td>456821-03-01</td> <td>Amendment C</td> </tr> </table>	<u>From</u>	<u>To</u>		456821-03-01	456821-03-01	Amendment C															
<u>From</u>	<u>To</u>																								
456821-03-01	456821-03-01	Amendment C																							

LTR 97 TEST EQUIPMENT SERVICE BULLETIN INDEX

This Index is available on the internet at: <http://nsd.es.northropgrumman.com/> (Click Support)

SB NUMBER/ FILE NUMBER	REV #.	REVISION DATE	ERA NO.	SUBJECT